PHENIX WEEKLY PLANNING



October 29, 2015 Carter Biggs

This Week

- 1. S-PHENIX H-Cal Prototype in 510 H-Bay
- 2. Continue VTX East work
- 3. Finish MPC-ex North testing
- 4. Survey North Beam Pipe
- 5. Remove North Scaffold
- 6. Move CM North

Next Week

- 1. Re-install VTX/FVTX West
- 2. Survey Central Magnet, VTX West, Center Beam Pipe, South Beam Pipe
- 3. Re-erect South Scaffold
- 4. Install MPC-Ex "sled"

2015 SHUTDOWN SHEDULE

June 19 th	End of Run Party
JUNE 22 ND	END OF RUN
June 23 rd	Roll out Shield Wall
June 25-30	Remove Shield Wall
June 24 - 29	Pixel Testing on VTX (Chuck, Eric)
July 1	Remove Collars, Move South Magnet south
July 2 – July 6	Disconnect & roll out East Carriage
July 6 – 7	Setup up IR for shut down work
July 6 – 10	De-Cable & remove East VTX/FVTX, move to 510
July 9 th	Erect Scaffold between south and central magnets
July 10 th	Set up MPC-ex "sled"
July 13 – 16	Remove MPC-ex south, MPC South Crystals
July 14 – 21	De-Cable & remove West VTX/FVTX, move to 510
July 17 – Aug 7	Repairs and upgrades to MPC-ex and MPC south in 510
July 17 – Sept 21	Repairs to East VTX/FVTX in 510
July 17 - Oct 19	Repairs to VTX/FVTX West in 510
July 29	Deliver and set up "Dance Floor" for Summer Sunday
July 31	Start to fold down East Carriage wings
Aug 2	SUMMER SUNDAY @ PHENIX
Aug 14 – 28	DC East and West Repairs
Aug 10 – 21	Replace & Troubleshoot MPC and MPC-ex South
Aug. 24 – 25	MuTr South Sta. 1 Repairs

2015 SHUTDOWN SCHEDULE (cont.)

Aug 24 – 26	Remove South scaffold and move CM south	
Aug 27 th	Erect Scaffold between CM and North magnet	
Aug 28 th	Install MPC-ex "sled" in north	
Aug. 28 – Sept. 4	MuTr North Sta. 1 Repairs	
Aug 31 – Sept 2	Remove MPC-ex North & MPC North crystals	
Sept 3 – 24	Repairs to MPC-ex & MPC North in 510	
	Re-install and re-cable VTX/FVTX West	
Sept 24 – Oct 8	Replace & Troubleshoot MPC North	
Oct 16 – 22	Replace MPC-ex North and troubleshoot	
Oct 28	Survey North Beam Pipe	
Oct 29	Remove North Scaffold and move CM North	
Oct 30	DC West Electronics Repairs	
Nov 2 – 4	Re-Install and re-cable VTX/FVTX West	
Nov 2	Erect South Scaffold	
Nov 3	Set up MPC-Ex South "sled"	
Nov 4 – 24	Re-install MPC-Ex South, wire, troubleshoot	
Nov 2 – 5	Survey CM, VTX West, and Central Beam Pipe	
Nov 3 – 20 1	Troubleshoot VTX/FVTX Systems	
Nov 23	Re-install VTV/FVTX East	
Nov 26	Survey VTX/FVTX East	/
Dec 1 – 4	Pren IR for Run 16	

2015 SHUTDOWN SCHEDULE (cont.)

Dec 4 Fold up "wings" on East Carriage

Dec 7- 9 Move in East Carriage


Dec 10 Fold down "wings" on East Carriage

Dec 11 – 15 Build Shield Wall

Dec 16 Move Shield Wall in

Dec 10 – 23 White, Pink, and Blue Sheeting

Jan 4 Start of Run 16



Injury Status:

FY16 YTD: DART - 1, TRC - 1, First Aid - 3

FY15: DART - 14, TRC - 24, First Aid - 51

FY14: DART - 18, TRC - 34, First Aid - 37

FY16 Injury Listing:

https://shsd.bnl.gov/occinj/BNLInjuries.aspx

Recent Injuries

10/21/15 Info Only An employee was injured in a motor vehicle accident while driving to work from a field office. This is not reportable.

Recent Events

10/20/15 Fire Rescue responded to Building 490 after an incremental heater unit was turned on and the fan motor Non-Reportable seized, which consequently produced a small amount of smoke. Fire Rescue confirmed that a fire did not exist. The unit was tagged out of service. There were no injuries. (Event Link)

From Gail Mattson, ALD for ES&H

Postings and signs are a key aspect of communicating important information to personnel. They provide essential information concerning hazards, work control measures, and resources such as PPE to ensure the safe conduct of work. Postings and signs should never be blocked or covered, because of the potential for undesirable safety, health, and/or regulatory compliance consequences. A recent incident illustrates this point.

In September, a job was conducted to paint the exterior of a building with spray-on primer. After completion of the first phase of the project, a Radiological Control Technician noticed the building's exterior radiological postings were covered to protect them from over-spray, making them unreadable.

Covering the signs during the spray painting was an appropriate action, however a contingency plan to address the unreadable signs was not determined and implemented because there was no prompt in worker planned work processes to do so. As a result, Radiological Control Division support personnel were not aware of this job. Therefore opportunities were missed to question the consequences of covering the radiological postings.

Fully legible signs/postings are critical to communicate work related information. Even when we follow the work planning steps, it is important to step back and look at the larger picture. A questioning attitude is essential for identifying changing conditions that can impact how work is conducted. -Gail

WHERE TO FIND PHENIX ENGINEERING INFO





13

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_SSint-page.htm